

# **Pumper Car<sup>®</sup> Uniflex<sup>™</sup> Ride-on Vehicle**

## **Safety Documentation**





Total Quality. Assured.

**Test Report**

Applicant : Columbia-Inland Corporation  
7160 SW Fir Loop Suite 201A Portland, OR 97223-8068 USA  
Attn :Randy Wilder

NUMBER : TSNH00380225  
Date : Sep 10,2021

Sample Description:

One (1) submitted sample said to be	
Item Name	quadricycle

Tests Conducted:

As requested by the applicant, for details refer to attached page(s).

Authorized By :  
For Intertek Testing Services  
(Tianjin) Ltd. Qingdao Branch

David Zhang  
Senior Manager



Intertek Testing Service (Tianjin) Ltd.,  
Qingdao Branch  
大祥(天津)应用技术服务有限公司  
青岛分公司

Building 11, No. 177, Zhuzhou Road,  
Laoshan District, Qingdao, 266000 China  
青岛市崂山区株洲路177号11号楼  
邮编266000

Tel +86 532 8099 3788  
Fax +86 532 8096 1802  
[www.intertek.com.cn](http://www.intertek.com.cn)  
[www.intertek.com](http://www.intertek.com)

**Test Report**

NUMBER : TSNH00380225

Conclusion:

<u>Tested Sample(s)/ Component(s)</u>	<u>Standard</u>	<u>Result</u>
Submitted Sample	U.S. ASTM F963-17 Physical and Mechanical Tests excluding the labelling requirement of section 5,6&7	Pass
Submitted Sample	U.S. ASTM F963-17 Flammability Test of Materials Other Than Textile Materials	Pass
Tested Component(s) of Submitted Samples	U.S. ASTM F963-17 Toxic Elements Test	Pass
(2)	U.S. Code of Federal Regulations title 16 part 1303 for total Lead content in surface coating	Pass
(2)	U.S. Consumer Product Safety Improvement Act 2008 title I, section 101 for total Lead content in surface coating	Pass
(1),(2),(3),(4),(5),(6),(7),(8), (9),(10),(11),(12),(13),(14), (15),(16)&(17)	U.S. Consumer Product Safety Improvement Act 2008 title I, section 101 for total Lead content in non-surface coating materials (substrate)	Pass
(8+10+11),(12+13+14)& (15+16+17)	US Consumer Product Safety Improvement Act 2008 Title I, Sec 108(a) & (b)(3) and US 16 CFR Part 1307 for Prohibition of Children's Toys and Child Care Articles Containing Specified Phthalates	Pass

.....  
To be continued

Authorized By :  
For Intertek Testing Services  
(Tianjin) Ltd. Qingdao Branch



David Zhang  
Senior Manager



**Test Report**

NUMBER : TSNH00380225

Photo



End of report